













Bi weekly Field Report











No. 67







Surveyor Zaw La
 Date visited 29 Aug 2019
 Time visited 15:30 pm

Weather Condition Cloudy
 The last time of heavy raining: Yesterday

No	Item	Condition	Narrative Description and Photos
1	(1.1) Water Supply System	Improved <input type="checkbox"/> Same <input checked="" type="checkbox"/> * Worse <input type="checkbox"/> <i>*as last week</i>	<p><u>Narrative Description</u></p> <p>Water distribution system has been supporting ninety household of the zone B resettled families. The new well was drilled and installed the pipe line and its necessary instruments because the underground water of the previous well includes iron hydroxide and yellowish mud that clogged in the iron removal tank. The current water condition is quite good and no iron hydroxide and yellowish mud are found.</p> <p><u>Photos</u></p> <div style="display: flex; flex-wrap: wrap;"> <div style="width: 50%; text-align: center;">  </div> <div style="width: 50%; text-align: center;">  </div> <div style="width: 50%; text-align: center;">  </div> <div style="width: 50%; text-align: center;">  </div> <div style="width: 50%; text-align: center;"> <p>Water from ground water tank</p>  </div> <div style="width: 50%; text-align: center;"> <p>Pipe line distribution water to houses</p>  </div> </div>

No	Item	Condition	Narrative Description and Photos
1	(1.2) Well	Improved <input type="checkbox"/> Same <input checked="" type="checkbox"/> * Worse <input type="checkbox"/> <i>*as last week</i>	<p>– Water from two open-wells is clean enough to use for drinking and living. There are eleven tube wells in the relocation site. Residents use the water basically from the pipeline distribution system so that the frequency of water usage from the tube wells is very low. To sustain the good condition of the tube wells, the leg pumps were kept and covered the PVC pipes with the caps till the residents use.</p>
			 
	(2) Drainage	Improved <input type="checkbox"/> Same <input checked="" type="checkbox"/> * Worse <input type="checkbox"/> <i>*as last week</i>	<p>– There is a little amount of water in the drainage canals at the moment.</p> <p>Photos</p>    
	(3) Road	Improved <input type="checkbox"/> Same <input checked="" type="checkbox"/> * Worse <input type="checkbox"/> <i>*as last week</i>	<p>– All the roads except 6th street are still dry and no problem for walking. 6th street is being damaged due to passing the heavy trucks that carry the soil to fill near the creek side. Therefore the exits of the drain at the 6th street are being blocked with the soil.</p> <p>Photos</p>

		 <p>Main Road - B</p>	 <p>1st Street</p>
		 <p>2nd Street Upper Block</p>	 <p>2nd Street Lower Block</p>
		 <p>3rd Street Upper Block</p>	 <p>3rd Street Lower Block</p>
		 <p>4th Street Upper Block</p>	 <p>4th Street Lower Block</p>
		 <p>5th Street</p>	 <p>6th Street</p>

			 <p>7th Street</p>	 <p>Site Village</p>
(4) Garbage Condition	Improved <input type="checkbox"/> Same <input checked="" type="checkbox"/> * Worse <input type="checkbox"/> <i>*as last week</i>	<ul style="list-style-type: none"> - The rubbish was dumped at the creek side and even in front of the houses before the enough garbage bins are provided. - Total fourteen garbage bins have been provided and placed at the corner of each road until the end of April. After April 2018, all the garbage bins are kept by the community leader of PAPs in the communal compound near the triangle junction of Main Road C and Upper Fourth Street. But starting from October, the garbage truck from township municipal office came and collected by giving its alarm along the Main Road B. <p>Photos</p>		
			 <p>Rubbishes in the creek near 1st street</p>	 <p>Rubbishes in the creek near 2nd street</p>
			 <p>The soil was filled near the creek of Main Road C in March</p>	 <p>The soil was filled near the creek of 6th Street in March</p>

(5) Fly proof toilet

Improved
 Same *
 Worse
 *as last week

- All of the fly proof toilets are used the residents.
- All of the toilets are repaired by the following procedures;
 - Installation the extra septic tanks beside the original
 - The pipe line system is installed from the extra tank to the ditch to flow the liquid out.

The toilet renovation plan was successfully done and there is no problem at the moment.

Condition	No. of HHs	
	This week condition	Previous week condition
Level 1	91	91
Level 2	0	0
Level 3	0	0
Level 4	0	0
No Toilet	0	0

<Evaluation Criteria>

Level 1

- Fly proof toilet is not needed to be repaired.
- No/rarely toilet unavailable

Level 2

- Fly proof toilet is needed to be repaired.
- Rarely toilet unavailable

Level 3

- Fly proof toilet is needed to be repaired.
- Often toilet unavailable
- As the result of filling the soil and also due to the heavy rain, some toilets are inconvenience to use.

Level 4

- Fly proof toilet is urgently needed to be repaired.
- Often toilet unavailable

Photos



House No. 83







House No. 46












House No. 74



House No. 21

	(6) Electricity	Improved <input type="checkbox"/> Same <input checked="" type="checkbox"/> * Worse <input type="checkbox"/> <i>*as last week</i>	<ul style="list-style-type: none"> – Residents get the electricity regularly. – Electric poles and transformer are being supported with the good foundations. – There are some pieces of wood under an electric pole of main road B and it's needed to clean up. <p>Photos</p>	
			 <p>Transformer No. 1</p>	 <p>Transformer No. 2</p>
			 <p>Transformer No. 3</p>	 <p>Electric poles of Main Road B and Main Road C</p>

No	Item	Condition	Description and Photos
2	(1)House Construction	No. of houses which are not completed (4)	<ul style="list-style-type: none"> – In plot No.9 and 10, three houses that are planned to build as the plots are owned by father and son. The second floors of these three houses are needed to be carried on. – Plot No. 66, the house construction for the first floor has been finished and the second floor is still needed to be carried on. <p>Photos</p>  <p>House No. 9</p>  <p>House No. 10</p>  <p>House No. 66</p>

3	Other Issues																		
(1). Drainage condition for rain water in the compounds	<p data-bbox="568 129 703 161"><u>Description</u></p> <table border="1" data-bbox="568 192 1155 427"> <thead> <tr> <th data-bbox="568 192 751 293" rowspan="2">Condition</th> <th colspan="2" data-bbox="751 192 1155 226">No. of HHs</th> </tr> <tr> <th data-bbox="751 226 935 293">This week condition</th> <th data-bbox="935 226 1155 293">Previous week condition</th> </tr> </thead> <tbody> <tr> <td data-bbox="568 293 751 327">Level 1</td> <td data-bbox="751 293 935 327">82</td> <td data-bbox="935 293 1155 327">82</td> </tr> <tr> <td data-bbox="568 327 751 360">Level 2</td> <td data-bbox="751 327 935 360">5</td> <td data-bbox="935 327 1155 360">5</td> </tr> <tr> <td data-bbox="568 360 751 394">Level 3</td> <td data-bbox="751 360 935 394">3</td> <td data-bbox="935 360 1155 394">3</td> </tr> <tr> <td data-bbox="568 394 751 427">Level 4</td> <td data-bbox="751 394 935 427">1</td> <td data-bbox="935 394 1155 427">1</td> </tr> </tbody> </table> <p data-bbox="568 461 847 492"><Evaluation Criteria></p> <p data-bbox="568 492 655 524">Level 1</p> <p data-bbox="568 524 1374 589">-No mud and no standing water with their own drainage system in their compound</p> <p data-bbox="568 589 655 620">Level 2</p> <p data-bbox="568 620 1139 651">-No mud and no standing water in their compound</p> <p data-bbox="568 651 663 683">Level 3</p> <p data-bbox="568 683 1230 714">- Some or little mud and standing water in their compound</p> <p data-bbox="568 714 655 745">Level 4</p> <p data-bbox="568 745 1155 777">-A lot of mud and standing water in their compound</p> <p data-bbox="568 810 1414 909">Remark: The compound of house no. 47 will not be muddy again as it has been renovated with concrete. Therefore the other photo for level 3 will be changed in the next report.</p> <p data-bbox="568 943 655 974">Photos</p> <div data-bbox="568 974 995 1290"> <p data-bbox="592 987 687 1019">Level 1</p>  <p data-bbox="592 1256 759 1288">House No. 31</p> </div> <div data-bbox="1023 974 1452 1290"> <p data-bbox="1046 987 1142 1019">Level 2</p>  <p data-bbox="1046 1256 1214 1288">House No. 19</p> </div> <div data-bbox="568 1301 995 1617"> <p data-bbox="592 1314 687 1346">Level 3</p>  <p data-bbox="592 1583 759 1615">House No. 64</p> </div> <div data-bbox="1023 1301 1452 1617"> <p data-bbox="1046 1314 1142 1346">Level 4</p>  <p data-bbox="1046 1583 1214 1615">House No. 84</p> </div> <div data-bbox="568 1650 995 1966"> <p data-bbox="592 1664 687 1695">Level 3</p>  <p data-bbox="592 1933 759 1964">House No. 75</p> </div> <div data-bbox="1023 1650 1452 1966"> <p data-bbox="1046 1664 1142 1695">Level 4</p>  <p data-bbox="1046 1933 1214 1964">House No. 88</p> </div>		Condition	No. of HHs		This week condition	Previous week condition	Level 1	82	82	Level 2	5	5	Level 3	3	3	Level 4	1	1
Condition	No. of HHs																		
	This week condition	Previous week condition																	
Level 1	82	82																	
Level 2	5	5																	
Level 3	3	3																	
Level 4	1	1																	

(2) Plantation

- In front of the compounds, the shady trees, fruit trees, flowering plants and vegetables are being planted.

Description

- In front of the compounds, the shade trees, fruit trees, flowering plants and vegetables are being planted.

Type	No. of HHs	Remarks
Shade tree	15	Albizzia, Indian almond, Neem tree, etc. HH No. 20, 40, 43, 48, 51, 57, 59, 61, 62, 67, 69, 72, 73, 77, 85
Fruit tree	37	Banana, Mango, sugar cane, coconut, citrus and jack fruit etc. HH No. 3, 15, 17, 20,21, 23, 28, 30, 31, 32, 34, 37, 40, 41, 48, 51, 52, 55, 57, 58, 59, 61, 62, 63, 67, 68, 70, 71, 72, 73, 77, 78, 82, 85, 86, 88
Vegetables	20	Chili, tomato, bitter gourd, Roselle, gourd, basils, eggplant etc. HH No. 12, 17, 21, 41, 49, 58, 59, 61, 62, 63, 67, 68, 70, 71, 72, 73, 77, 82, 85, 86
Flowering plant	31	Jasmine, poinsettia, orchid, kiss me quick, etc. HH No. 3, 5, 6, 8, 10, 12, 13, 14, 17, 20, 21, 22, 23, 29, 30, 31, 32, 46, 48, 58, 59, 61, 62, 65, 67, 68, 69, 72, 77, 78, 86

Photos,



(3) Livestock

Description

-The chicken, geoses and ducks are being raised.

Type	No. of HHs	Remarks
Chicken	6	HH No. 13, 14, 21, 59, 67, 78
Duck	3	HH No.12
Goose	2	HH No. 40, 67

Photos



House No. 67



House No. 78