

Weekly Field Report

No. 30


Surveyor: Zaw La

Date Visited: 25.5.2015






Time Visited: 9:30to 11:30

Weather Condition: Sunny


The last time of heavy raining: -

No	Item	Condition	Description and Photos
1	Condition of -		
	(1). Well	Improved <input type="checkbox"/> Same <input checked="" type="checkbox"/> * Worse <input type="checkbox"/> <i>*as last week</i>	Description & Photos: -See ANNEX.1 - Two wells and all hand pumps except near transformer are well functioned, water is clean and water amount is enough to use as the raining season is nearer and underground water level is raising up. Therefore no problem has heard so far.
	(2). Drainage	Improved <input type="checkbox"/> Same <input checked="" type="checkbox"/> * Worse <input type="checkbox"/> <i>*as last week</i>	<p><u>Description</u> -Water level in the drainage canal is slightly increased than last week because there was a little rain for three days due to the typhoon.</p> <p><u>Photos</u></p>  <p>The drainage canals are cleaned by constructors; Mr. Bobby and Ko Win Thein.</p>


	(3). Road	Improved <input type="checkbox"/> Same <input checked="" type="checkbox"/> * Worse <input type="checkbox"/> <i>*as last week</i>	<u>Description</u> -The roads are a bit wet, but no problem for walking so far.
			<u>Photos</u> 
	(4). Garbage Condition	Improved <input type="checkbox"/> Same <input checked="" type="checkbox"/> * Worse <input type="checkbox"/>	<u>Description</u> -Garbage pit is used by people. -Garbage pit is over full. -There are some smells from garbage pit. -People throw garbage at the backside of Third Row. 


			 																				
			The drainage canal is cleaned by constructor.																				
No	Item	Condition	Description and Photos																				
1	(5). Fly proof toilet	Improved <input type="checkbox"/> Same <input checked="" type="checkbox"/> * Worse <input type="checkbox"/> <i>*as last week</i>	<p><u>Description</u> -All of fly proof toilets are used by people.</p> <table border="1"> <thead> <tr> <th rowspan="2">Condition</th> <th colspan="2">No. of HHs</th> </tr> <tr> <th>This week condition</th> <th>Previous week condition</th> </tr> </thead> <tbody> <tr> <td>Level 1</td> <td>42</td> <td>42</td> </tr> <tr> <td>Level 2</td> <td>21</td> <td>21</td> </tr> <tr> <td>Level 3</td> <td>0</td> <td>0</td> </tr> <tr> <td>Level 4</td> <td>0</td> <td>0</td> </tr> <tr> <td>No Toilet</td> <td>5</td> <td>5</td> </tr> </tbody> </table> <p><Evaluation Criteria> Level 1 -No need to repair fly proof toilet -No/rarely toilet unavailable Level 2 -Need to repair fly proof toilet -Rarely toilet unavailable Level 3 -Need to repair fly proof toilet -Often toilet unavailable Level 4 -Need to repair urgently fly proof toilet -Often toilet unavailable</p> <p><u>Photos</u></p>   	Condition	No. of HHs		This week condition	Previous week condition	Level 1	42	42	Level 2	21	21	Level 3	0	0	Level 4	0	0	No Toilet	5	5
Condition	No. of HHs																						
	This week condition	Previous week condition																					
Level 1	42	42																					
Level 2	21	21																					
Level 3	0	0																					
Level 4	0	0																					
No Toilet	5	5																					
	(6). Electricity	Improved <input type="checkbox"/> Same <input checked="" type="checkbox"/> * Worse <input type="checkbox"/>	<p><u>Description</u> -Electricity comes regularly. -Electric poles and transformer are supported in good foundation.</p>																				

		*as last week	<p><u>Photos</u></p> 
--	--	---------------	---

No	Item	Condition	Description and Photos
2	House Construction	No. of houses not completed (2)	<p><u>Description</u></p> <p>-HH No.1 is almost renovated except fancying and ceiling inside the house, and it will suppose to be finished within next week.</p> <p>-HH No.5, the construction for kitchen, toilet and water tank seems stopped.</p> <p><u>Photos</u></p> 
3	Living Status of PAPs (Sold house, renting, etc.)	<p><u>Description</u></p> <p>(1) House ownership</p> <p>(1)-1 No. of house that are owned by PAPs (48)</p> <p>(1)-2 No. of house that were sold (20)</p> <p>(2) Living condition</p> <p>(2)-1 No. of houses where PAPs live (38)</p> <p>(2)-2 No. of houses where not original PAPs lives (22)</p> <p>(2)-3 No. of houses where nobody lives (8)</p>	<p>Location Map: See ANNEX.2</p>

<p>4</p>	<p>Other issues</p> <p>(1). Drainage condition for rain water in their compounds</p>	<p><u>Description</u></p> <p>-Rainy season is going to start. -Most of the compounds are a bit wet.</p> <table border="1" data-bbox="451 317 998 541"> <thead> <tr> <th rowspan="2">Condition</th> <th colspan="2">No. of HHs</th> </tr> <tr> <th>This week condition</th> <th>Previous week condition</th> </tr> </thead> <tbody> <tr> <td>Level 1</td> <td>14</td> <td>14</td> </tr> <tr> <td>Level 2</td> <td>30</td> <td>30</td> </tr> <tr> <td>Level 3</td> <td>20</td> <td>20</td> </tr> <tr> <td>Level 4</td> <td>4</td> <td>4</td> </tr> </tbody> </table> <p><Evaluation Criteria></p> <p>Level 1 -No mud and no standing water with their own drainage system in their compound</p> <p>Level 2 -No mud and no standing water in their compound</p> <p>Level 3 - Some or little mud and standing water in their compound</p> <p>Level 4 -A lot of mud and standing water in their compound</p> <div data-bbox="483 915 1386 1579"> </div> <p>Brick access ways are constructed for almost all houses those are needed to do so. Example: see photo of HH No. 14.</p>	Condition	No. of HHs		This week condition	Previous week condition	Level 1	14	14	Level 2	30	30	Level 3	20	20	Level 4	4	4
Condition	No. of HHs																		
	This week condition	Previous week condition																	
Level 1	14	14																	
Level 2	30	30																	
Level 3	20	20																	
Level 4	4	4																	
<p>4</p>	<p>(2) Plantation</p>	<p><u>Description</u></p> <p>-In front of their compounds, they planted shady trees, fruit trees, vegetables and floral plants.</p> <table border="1" data-bbox="451 1793 1365 1896"> <thead> <tr> <th>Type</th> <th>No. of HHs</th> <th>Remarks</th> </tr> </thead> <tbody> <tr> <td>Shady tree</td> <td>12</td> <td>Albizzia, Indian almond, etc.</td> </tr> </tbody> </table>	Type	No. of HHs	Remarks	Shady tree	12	Albizzia, Indian almond, etc.											
Type	No. of HHs	Remarks																	
Shady tree	12	Albizzia, Indian almond, etc.																	

			HH No. 2, 3, 14, 19, 20, 21, 25, 27, 29, 32, 41 and 65																		
	Fruit tree	24	Banana, Mango, sugarcane, coconut, citrus, etc. HH No. 2, 3, 4, 7, 8, 9, 11, 17, 21,24, 25, 27, 33, 37, 38, 39, 41, 43, 45, 46, 47, 48, 54 and 65																		
	Vegetable	10	Spices, peas, roselle, etc. HH No. 22, 23, 25, 27, 38, 39, 40, 42,45 and 63																		
	Floral plant	20	Many species. HH No. 2, 9, 14, 15, 17,21, 23, 27, 32, 33, 38, 39, 40, 41, 42, 43, 47, 48, 58 and 65																		
	<u>Photos</u>																				
																					
4	(3) Livestock	<u>Description</u> -They are raising chicken, ducks, goats, pigs and cows. -Even though they have cows, they do not keep their cows in relocation site instead they keep in their farms or other places.																			
		<table border="1"> <thead> <tr> <th>Type</th> <th>No. of HHs</th> <th>Remarks</th> </tr> </thead> <tbody> <tr> <td>Cow</td> <td>5</td> <td>HH No. 3, 18, 42, 47 and 54</td> </tr> <tr> <td>Pig</td> <td>-</td> <td>-</td> </tr> <tr> <td>Goat</td> <td>1</td> <td>HH.47</td> </tr> <tr> <td>Chicken and ducks</td> <td>15</td> <td>HH No. 4, 8, 12, 14, 28, 30, 32, 41, 47, 50, 51, 52, 55, 56 and 62</td> </tr> <tr> <td></td> <td></td> <td></td> </tr> </tbody> </table>	Type	No. of HHs	Remarks	Cow	5	HH No. 3, 18, 42, 47 and 54	Pig	-	-	Goat	1	HH.47	Chicken and ducks	15	HH No. 4, 8, 12, 14, 28, 30, 32, 41, 47, 50, 51, 52, 55, 56 and 62				
Type	No. of HHs	Remarks																			
Cow	5	HH No. 3, 18, 42, 47 and 54																			
Pig	-	-																			
Goat	1	HH.47																			
Chicken and ducks	15	HH No. 4, 8, 12, 14, 28, 30, 32, 41, 47, 50, 51, 52, 55, 56 and 62																			

		<p><u>Photos</u></p> 
5	Remarks	<p>For avoiding from flood, each of the PAPs' compounds have been fenced by retaining wall, the stands of the houses are painted by water proofing paint or making concrete protection. Moreover each of the PAPs' compound will be going to fill with sandy soil soon.</p>

ANNEX.1

As of 11.5.2015

Water is clean and has no sand, no clay and no smell. People use this well for cooking, washing and drinking. But It needs to be set up a set of a pulley wheel, bucket and a rope for convenience using the well.



The well is in good situation. No smell. Water is clean and people living nearby are using this well. But it needs to be set up a set of a pulley wheel, bucket and a rope for convenience using the well.




1

This hand pump is functioned very well. Water is clean and everyone nearby using this hand pump.

This hand pump is also functioned very well. Water is clean and everyone nearby using this hand pump.






Hand pump isn't functioned.



This hand pump is also functioned very well. Water is clean and everyone living nearby using this hand pump. Now the raining season is going to be started and the underground water level is raising up and therefore the amount of having clean water is pretty enough to use.

This hand pump is also functioned very well. Water is clean and everyone living nearby using this hand pump. Now the raining season is going to be started and the underground water level is raising up and therefore the amount of having clean water is pretty enough to use.



-  Closed Well
-  New Well (Hand pump)
-  Open Well
-  Hand Pump
-  Private Well