

Weekly Field Report

No. 6


Surveyor: Sithu Nyein



Date Visited: 24.9.2014







Time Visited: 9:30 to 11:00


Weather Condition: Sunny

The last time of heavy raining: _____ -


No	Item	Condition	Description and Photos
1	Condition of -		
	(1). Well	Improved <input type="checkbox"/> Same <input checked="" type="checkbox"/> * Worse <input type="checkbox"/> <i>*as last week</i>	Description & Photos: -See ANNEX.1 -Hand Pumps of Well No.6 and 11 are needed to repair.
	(2). Drainage	Improved <input type="checkbox"/> Same <input checked="" type="checkbox"/> Worse <input type="checkbox"/> <i>*as last week</i>	<u>Description</u> -Water level in the drainage canal is near to the bottom. <u>Photos</u> 
	(3). Road	Improved <input type="checkbox"/> Same <input checked="" type="checkbox"/> * Worse <input type="checkbox"/> <i>*as last week</i>	<u>Description</u> -The roads are almost dry and no problem for traffic as a whole.

			<p><u>Photos</u></p> 
	<p>(4). Garbage Condition</p>	<p>Improved <input checked="" type="checkbox"/> Same <input type="checkbox"/> Worse <input type="checkbox"/></p>	<p><u>Description</u></p> <ul style="list-style-type: none"> -Garbage pit is used by people. -Smells are emerging from garbage pit. -Garbage pit is nearly full. 

No	Item	Condition	Description and Photos																				
1	(5). Fly proof toilet	Improved <input type="checkbox"/> Same <input checked="" type="checkbox"/> Worse <input type="checkbox"/> <i>*as last week</i>	<p><u>Description</u> -All of fly proof toilets are being used by people.</p> <table border="1"> <thead> <tr> <th rowspan="2">Condition</th> <th colspan="2">No. of HHs</th> </tr> <tr> <th>This week condition</th> <th>Previous week condition</th> </tr> </thead> <tbody> <tr> <td>Level 1</td> <td>42</td> <td>42</td> </tr> <tr> <td>Level 2</td> <td>21</td> <td>21</td> </tr> <tr> <td>Level 3</td> <td>0</td> <td>0</td> </tr> <tr> <td>Level 4</td> <td>0</td> <td>0</td> </tr> <tr> <td>No Toilet</td> <td>5</td> <td>5</td> </tr> </tbody> </table> <p><Evaluation Criteria> Level 1 -No need to repair fly proof toilet -No/rarely toilet unavailable Level 2 -Need to repair fly proof toilet -Rarely toilet unavailable Level 3 -Need to repair fly proof toilet -Often toilet unavailable Level 4 -Need to repair urgently fly proof toilet -Often toilet unavailable</p> <p><u>Photos</u></p>   	Condition	No. of HHs		This week condition	Previous week condition	Level 1	42	42	Level 2	21	21	Level 3	0	0	Level 4	0	0	No Toilet	5	5
Condition	No. of HHs																						
	This week condition	Previous week condition																					
Level 1	42	42																					
Level 2	21	21																					
Level 3	0	0																					
Level 4	0	0																					
No Toilet	5	5																					
	(6). Electricity	Improved <input type="checkbox"/> Same <input checked="" type="checkbox"/> Worse <input type="checkbox"/> <i>*as last week</i>	<p><u>Description</u> -Electricity is coming regularly -Electric poles and transformer are supported in good foundation.</p> <p><u>Photos</u></p>   																				

No	Item	Condition	Description and Photos																	
2	House Construction	No. of houses not completed (2)	<p><u>Description</u></p> <p>-HH No.1 doesn't have ladder and nobody is living -In HH No.5, the construction for kitchen, toilet and water tank seems stopped. Nobody lives. -In HH No.5, sun shade of this house has been repaired.</p> <p><u>Photos</u></p> 																	
3	Living Status of PAPs (Sold house, renting, etc.)	<p><u>Description</u></p> <p>(1) House ownership (1)-1 No. of house that are owned by PAPs (49) (1)-2 No. of house that were sold (19)</p> <p>(2) Living condition (2)-1 No. of houses where PAPs live (37) (2)-2 No. of houses where not original PAPs lives (26) (2)-3 No. of houses where nobody lives (5)</p> <p>Yellow= Changes from previous week</p>	<p>Location Map: See ANNEX.2</p>																	
4	Other issues		<p>(1). Drainage condition for rain water in their compounds</p> <p><u>Description</u></p> <p>-In most of the compounds, they become dry because of less rains.</p> <table border="1" data-bbox="400 1641 987 1883"> <thead> <tr> <th rowspan="2">Condition</th> <th colspan="2">No. of HHs</th> </tr> <tr> <th>This week condition</th> <th>Previous week condition</th> </tr> </thead> <tbody> <tr> <td>Level 1</td> <td>12</td> <td>11</td> </tr> <tr> <td>Level 2</td> <td>32</td> <td>26</td> </tr> <tr> <td>Level 3</td> <td>16</td> <td>18</td> </tr> <tr> <td>Level 4</td> <td>8</td> <td>13</td> </tr> </tbody> </table> <p><Evaluation Criteria></p> <p>Level 1 -No mud and no standing water with their own drainage system in their compound</p> <p>Level 2</p>	Condition	No. of HHs		This week condition	Previous week condition	Level 1	12	11	Level 2	32	26	Level 3	16	18	Level 4	8	13
Condition	No. of HHs																			
	This week condition	Previous week condition																		
Level 1	12	11																		
Level 2	32	26																		
Level 3	16	18																		
Level 4	8	13																		

-No mud and no standing water in their compound
Level 3
 - Some or little mud and standing water in their compound
Level 4
 -A lot of mud and standing water in their compound



4 (2)
 Plantation

Description
 -In front of their compounds, they planted shady trees, fruit trees, vegetables and floral plants.

Type	No. of HHs	Remarks
Shady tree	12	Albizzia, Indian almond, etc. HH No. 2, 3, 14, 19, 20, 21, 25, 27, 29, 32, 41 and 65
Fruit tree	24	Banana, Mango, sugarcane, coconut, citrus, etc. HH No. 2, 3, 4, 7, 8, 9, 11, 17, 21,24, 25, 27, 33, 37, 38, 39, 41, 43, 45, 46, 47, 48, 54 and 65
Vegetable	10	Spices, peas, roselle, etc. HH No. 22, 23, 25, 27, 38, 39, 40, 42,45 and 63
Floral plant	20	Many species. HH No. 2, 9, 14, 15, 17,21, 23, 27, 32, 33, 38, 39, 40, 41, 42, 43, 47, 48, 58 and 65

Photos




HH No.17



HH No. 25



HH No. 65



Near well No.8

4 (3) Livestock

Description


-They are raising chicken, ducks, goats, pigs and cows.
 -Even though they have cows, they do not keep their cows in relocation site instead they keep in their farms or other places.

Type	No. of HHs	Remarks
Cow	5	HH No. 3, 18, 42, 47 and 54
Pig	1	HH No. 2
Goat	2	HH No. 50 and 51
Chicken and ducks	15	HH No. 4, 8, 12, 14, 28, 30, 32, 41, 47, 50, 51, 52, 55, 56 and 62

Photos



		
5	Remarks	



Water is clean and has no sand, no clay and no smell. People are using this well for cooking and washing. Sometimes they are drinking



Hand pump is functioned. Water is clean and has no sand, no clay but it has smell of mud. People are using this well for washing.



Hand pump isn't functioned very well. It is need to repair the washer. Water is clean and has no sand, no clay and no smell. People are using this well for cooking and washing.



Hand pump isn't functioned.

Water is milk in color and has no sand, no clay and no smell. People are not using this well.



Hand pump is functioned. Water is clean, and has no sand, no clay but it has smell of mud. People are using this well for washing.



-  **Closed Well**
-  **New Well (Hand pump)**
-  **Open Well**
-  **Hand Pump**
-  **Private Well**

Hand pump is functioned. Water is clean and has no sand, no clay, and no smell. People are using this well for cooking and washing. Sometimes they are drinking.

