

Weekly Field Report

No. 5


Surveyor: Sithu Nyein



Date Visited: 16.9.2014







Time Visited: 9:00 to 10:30


Weather Condition: Sunny and partly cloudy

The last time of heavy raining: 5 days ago

No	Item	Condition	Description and Photos
1	Condition of -		
	(1). Well	Improved <input type="checkbox"/> Same <input checked="" type="checkbox"/> * Worse <input type="checkbox"/> <i>*as last week</i>	Description & Photos: -See ANNEX.1 -Hand pump of well No.8 has been repaired by replacement of the parts of hand pump of Well No.11. -Hand Pumps of Well No.6 and 11 are needed to repair.
	(2). Drainage	Improved <input type="checkbox"/> Same <input checked="" type="checkbox"/> Worse <input type="checkbox"/> <i>*as last week</i>	Description -Water level in the drainage canal is near to the bottom.  Photos 
	(3). Road	Improved <input type="checkbox"/> Same <input checked="" type="checkbox"/> * Worse <input type="checkbox"/> <i>*as last week</i>	Description -There are some puddles and partly muddy areas but the roads are almost dry and no problem for traffic as a whole.

			<p><u>Photos</u></p> 
(4). Garbage Condition	<p>Improved <input checked="" type="checkbox"/></p> <p>Same <input type="checkbox"/></p> <p>Worse <input type="checkbox"/></p>	<p><u>Description</u></p> <ul style="list-style-type: none"> <li>-Water level near garbage pit becomes lower.</li> <li>-Garbage pit is used by people.</li> <li>-Smells are emerging from garbage pit.</li> <li>-Garbage near the electrical transformer and in the drainage canals is collected and put together into the garbage pit. So this places become clean.</li> </ul>	

No	Item	Condition	Description and Photos																				
1	(5). Fly proof toilet	Improved <input type="checkbox"/> Same <input checked="" type="checkbox"/> Worse <input type="checkbox"/> <i>*as last week</i>	<p><u>Description</u> -All of fly proof toilets are being used by people.</p> <table border="1"> <thead> <tr> <th rowspan="2">Condition</th> <th colspan="2">No. of HHs</th> </tr> <tr> <th>This week condition</th> <th>Previous week condition</th> </tr> </thead> <tbody> <tr> <td>Level 1</td> <td>42</td> <td>42</td> </tr> <tr> <td>Level 2</td> <td>21</td> <td>21</td> </tr> <tr> <td>Level 3</td> <td>0</td> <td>0</td> </tr> <tr> <td>Level 4</td> <td>0</td> <td>0</td> </tr> <tr> <td>No Toilet</td> <td>5</td> <td>5</td> </tr> </tbody> </table> <p><b>&lt;Evaluation Criteria&gt;</b>  <b>Level 1</b>            -No need to repair fly proof toilet            -No/rarely toilet unavailable  <b>Level 2</b>            -Need to repair fly proof toilet            -Rarely toilet unavailable  <b>Level 3</b>            -Need to repair fly proof toilet            -Often toilet unavailable  <b>Level 4</b>            -Need to repair urgently fly proof toilet            -Often toilet unavailable</p> <p><u>Photos</u></p>   	Condition	No. of HHs		This week condition	Previous week condition	Level 1	42	42	Level 2	21	21	Level 3	0	0	Level 4	0	0	No Toilet	5	5
Condition	No. of HHs																						
	This week condition	Previous week condition																					
Level 1	42	42																					
Level 2	21	21																					
Level 3	0	0																					
Level 4	0	0																					
No Toilet	5	5																					
	(6). Electricity	Improved <input type="checkbox"/> Same <input checked="" type="checkbox"/> Worse <input type="checkbox"/> <i>*as last week</i>	<p><u>Description</u> -Electricity is coming regularly -Electric poles and transformer are supported in good foundation.</p> <p><u>Photos</u></p>   																				

No	Item	Condition	Description and Photos																	
2	House Construction	No. of houses not completed (2)	<p><u>Description</u></p> <p>-HH No.1 doesn't have ladder and nobody is living            -In HH No.5, the construction for kitchen, toilet and water tank seems stopped. Nobody lives.            -In HH No.5, sun shade of this house is collapsed due to wind. Wind is not so strong but the quality of the sun shade is not so good enough.</p> <p><u>Photos</u></p> 																	
3	Living Status of PAPs (Sold house, renting, etc.)	<p><u>Description</u></p> <p>(1) House ownership            (1)-1 No. of house that are owned by PAPs (49)            (1)-2 No. of house that were sold (19)</p> <p>(2) Living condition            (2)-1 No. of houses where PAPs live (37)            (2)-2 No. of houses where not original PAPs lives (25)            (2)-3 No. of houses where nobody lives (6 )</p>	<p>Location Map: See ANNEX.2</p>																	
4	Other issues		<p>(1). Drainage condition for rain water in their compounds</p> <p><u>Description</u></p> <p>-There are some puddles and muddy areas in most of the compounds.</p> <table border="1" data-bbox="400 1641 987 1883"> <thead> <tr> <th rowspan="2">Condition</th> <th colspan="2">No. of HHs</th> </tr> <tr> <th>This week condition</th> <th>Previous week condition</th> </tr> </thead> <tbody> <tr> <td>Level 1</td> <td>11</td> <td>10</td> </tr> <tr> <td>Level 2</td> <td>26</td> <td>26</td> </tr> <tr> <td>Level 3</td> <td>18</td> <td>18</td> </tr> <tr> <td>Level 4</td> <td>13</td> <td>14</td> </tr> </tbody> </table> <p><b>&lt;Evaluation Criteria&gt;</b></p> <p><b>Level 1</b>            -No mud and no standing water with their own drainage system in their compound</p> <p><b>Level 2</b></p>	Condition	No. of HHs		This week condition	Previous week condition	Level 1	11	10	Level 2	26	26	Level 3	18	18	Level 4	13	14
Condition	No. of HHs																			
	This week condition	Previous week condition																		
Level 1	11	10																		
Level 2	26	26																		
Level 3	18	18																		
Level 4	13	14																		

-No mud and no standing water in their compound  
**Level 3**  
 - Some or little mud and standing water in their compound  
**Level 4**  
 -A lot of mud and standing water in their compound



**4** (2)  
 Plantation

Description  
 -In front of their compounds, they planted shady trees, fruit trees, vegetables and floral plants.

Type	No. of HHs	Remarks
Shady tree	12	Albizzia, Indian almond, etc. HH No. 2, 3, 14, 19, 20, 21, 25, 27, 29, 32, 41 and 65
Fruit tree	24	Banana, Mango, sugarcane, coconut, citrus, etc. HH No. 2, 3, 4, 7, 8, 9, 11, 17, 21,24, 25, 27, 33, 37, 38, 39, 41, 43, 45, 46, 47, 48, 54 and 65
Vegetable	10	Spices, peas, roselle, etc. HH No. 22, 23, 25, 27, 38, 39, 40, 42,45 and 63
Floral plant	20	Many species. HH No. 2, 9, 14, 15, 17,21, 23, 27, 32, 33, 38, 39, 40, 41, 42, 43, 47, 48, 58 and 65

Photos



**4** (3) Livestock

Description

-They are raising chicken, ducks, goats, pigs and cows.  
 -Even though they have cows, they do not keep their cows in relocation site instead they keep in their farms or other places.

Type	No. of HHs	Remarks
Cow	5	HH No. 3, 18, 42, 47 and 54
Pig	1	HH No. 2
Goat	2	HH No. 50 and 51
Chicken and ducks	15	HH No. 4, 8, 12, 14, 28, 30, 32, 41, 47, 50, 51, 52, 55, 56 and 62

Photos





<b>5</b>	<b>Remarks</b> -Garbage throughout the relocation site was collected and put together into garbage pit on Monday ( 15 <sup>th</sup> September 2014) by PAPs. -U San Pyae Wai from HH No.60 passed away on Monday early morning ( 15 <sup>th</sup> September 2014) because of motorbike accident.
----------	--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------

