

Weekly Field Report

No. 2


Surveyor: Sithu Nyein


Date Visited: 26.8.2014







Time Visited: 14:00 to 16:00







Weather Condition: Sunny


The last time of heavy raining: 6 days ago





No	Item	Condition	Description and Photos
1	Condition of -		
	(1). Well	Improved <input type="checkbox"/> Same <input type="checkbox"/> Worse <input checked="" type="checkbox"/>	<u>Description & Photos:</u> -See ANNEX.1 -Hand pumps of well No.6 and No.9 are needed to repair.
	(2). Drainage	Improved <input checked="" type="checkbox"/> Same <input type="checkbox"/> Worse <input type="checkbox"/>	<u>Description</u> -Water level in the drainage canal is near to the bottom. <u>Photos</u> 







No	Item	Condition	Description and Photos
1	(3). Road	Improved <input type="checkbox"/> Same <input checked="" type="checkbox"/> * Worse <input type="checkbox"/> <i>*as last week</i>	<p><u>Description</u></p> <p>-There are some puddles and partly muddy areas but the roads are almost dry and no problem for traffic as a whole.</p> <hr/> <p><u>Photos</u></p> 


No	Item	Condition	Description and Photos
1	(4). Garbage Condition	Improved <input checked="" type="checkbox"/> Same <input type="checkbox"/> Worse <input type="checkbox"/>	<p><u>Description</u></p> <ul style="list-style-type: none"> -Water level near garbage pit becomes lower. -Garbage pit is used by some people. -Especially people who live in third row throw away the garbage in the backside of their compounds over the fence. -Some people put the garbage near electrical transformer. -Garbage is thrown away in the drainage canal. <div style="display: flex; flex-wrap: wrap; justify-content: space-around;"> <div style="text-align: center; margin: 5px;">  <p>Garbage Pit</p> </div> <div style="text-align: center; margin: 5px;">  <p>Garbage Pit</p> </div> <div style="text-align: center; margin: 5px;">  <p>Garbage Pit</p> </div> <div style="text-align: center; margin: 5px;">  <p>Garbage at the backside of HH No.49</p> </div> <div style="text-align: center; margin: 5px;">  <p>Near transformer</p> </div> <div style="text-align: center; margin: 5px;">  <p>Drainage canal near HH No.48</p> </div> </div>

No	Item	Condition	Description and Photos																		
1	(5). Fly proof toilet	Improved <input type="checkbox"/> Same <input checked="" type="checkbox"/> * Worse <input type="checkbox"/> <i>*as last week</i>	<u>Description</u> -All of fly proof toilets are being used by people.	<u>Photos</u>  																	
			<table border="1"> <thead> <tr> <th rowspan="2">Condition</th> <th colspan="2">No. of HHs</th> </tr> <tr> <th>This week condition</th> <th>Previous week condition</th> </tr> </thead> <tbody> <tr> <td>Level 1</td> <td>42</td> <td>42</td> </tr> <tr> <td>Level 2</td> <td>21</td> <td>21</td> </tr> <tr> <td>Level 3</td> <td>0</td> <td>0</td> </tr> <tr> <td>Level 4</td> <td>0</td> <td>0</td> </tr> <tr> <td>No Toilet</td> <td>5</td> <td>5</td> </tr> </tbody> </table> <Evaluation Criteria> Level 1 -No need to repair fly proof toilet -No/rarely toilet unavailable Level 2 -Need to repair fly proof toilet -Rarely toilet unavailable Level 3 -Need to repair fly proof toilet -Often toilet unavailable Level 4 -Need to repair urgently fly proof toilet -Often toilet unavailable	Condition	No. of HHs		This week condition	Previous week condition	Level 1	42	42	Level 2	21	21	Level 3	0	0	Level 4	0	0	No Toilet
Condition	No. of HHs																				
	This week condition	Previous week condition																			
Level 1	42	42																			
Level 2	21	21																			
Level 3	0	0																			
Level 4	0	0																			
No Toilet	5	5																			
(6). Electricity		Improved <input type="checkbox"/> Same <input checked="" type="checkbox"/> * Worse <input type="checkbox"/> <i>*as last week</i>	<u>Description</u> -Electricity is coming regularly. -Electric poles and transformer are supported in good foundation.	<u>Photos</u>    																	

No	Item	Condition	Description and Photos
2	House Construction	No. of houses not completed (2)	<p><u>Description</u></p> <p>-HH No.1 doesn't have ladder and nobody is living. -In HH No.5, the construction for kitchen, toilet and water tank seems stopped. Nobody lives. -In HH No.5, sun shade of this house is collapsed due to wind. Wind is not so strong but the quality of the sun shade is not so good enough.</p> <p><u>Photos</u></p> 
3	Living Status of PAPs (Sold house, renting, etc.)	<p><u>Description</u></p> <p>(1) House ownership (1)-1 No. of sold house that are owned by PAPs (49) (1)-2 No. of sold house that were sold (19)</p> <p>(2) Living Condition (2)-1 No. of houses where PAPs live (37) (2)-2 No. of houses where not original PAPs live (24) (2)-3 No. of houses where nobody lives (7)</p> <p>Yellow = changes from last week</p> <p>-HH No.31 is rented by people, nobody is living before and it is sold house. -In HH No.5, nobody is living now.</p>	<p>Location Map: See ANNEX.2</p>

No	Item	Description and Photos																	
4	Other issues (1). Drainage condition for rain water in their compounds	<p><u>Description</u> -In this week, there is no heavy rain. -But there are some puddles and muddy areas in most of the compounds.</p> <table border="1"> <thead> <tr> <th rowspan="2">Condition</th> <th colspan="2">No. of HHs</th> </tr> <tr> <th>This week condition</th> <th>Previous week condition</th> </tr> </thead> <tbody> <tr> <td>Level 1</td> <td>6</td> <td>6</td> </tr> <tr> <td>Level 2</td> <td>28</td> <td>17</td> </tr> <tr> <td>Level 3</td> <td>23</td> <td>28</td> </tr> <tr> <td>Level 4</td> <td>11</td> <td>17</td> </tr> </tbody> </table> <p><Evaluation Criteria> Level 1 -No mud and no standing water with their own drainage system in their compound Level 2 -No mud and no standing water in their compound Level 3 - Some or little mud and standing water in their compound Level 4 -A lot of mud and standing water in their compound</p> <p><u>Photos</u></p> <div style="display: flex; flex-wrap: wrap;"> <div style="width: 50%; text-align: center;">  <p>HH No. 47</p> <p>Level 1</p> </div> <div style="width: 50%; text-align: center;">  <p>HH No. 14</p> <p>Level 2</p> </div> <div style="width: 50%; text-align: center;">  <p>HH No. 52</p> <p>Level 3</p> </div> <div style="width: 50%; text-align: center;">  <p>HH No. 11</p> <p>Level 4</p> </div> </div>	Condition	No. of HHs		This week condition	Previous week condition	Level 1	6	6	Level 2	28	17	Level 3	23	28	Level 4	11	17
Condition	No. of HHs																		
	This week condition	Previous week condition																	
Level 1	6	6																	
Level 2	28	17																	
Level 3	23	28																	
Level 4	11	17																	

No	Item	Description and Photos
4	(2)Plantation	<p data-bbox="400 237 544 271"><u>Description</u></p> <p data-bbox="400 271 1382 338">-In front of their compounds, they planted shady trees, fruit trees, vegetables and floral plants.</p> <p data-bbox="400 342 488 376"><u>Photos</u></p> <div data-bbox="432 416 895 763">  <p data-bbox="735 421 879 465">HH No. 9</p> </div> <div data-bbox="940 416 1402 763">  <p data-bbox="1259 421 1402 465">HH No. 17</p> </div> <div data-bbox="432 792 895 1140">  <p data-bbox="735 797 879 842">HH No. 23</p> </div> <div data-bbox="940 792 1402 1140">  <p data-bbox="1259 797 1402 842">HH No. 41</p> </div> <div data-bbox="432 1169 895 1516">  <p data-bbox="735 1173 879 1218">HH No. 45</p> </div> <div data-bbox="940 1169 1402 1516">  <p data-bbox="1259 1173 1402 1218">HH No. 65</p> </div>
5	Remarks	



Water is clean and has no sand, no clay and no smell. People are using this well for cooking and washing. Sometimes they are drinking.



Hand pump is functioned. Water is clean and has no sand, no clay but it has smell of mud. People are not using this well



Hand pump isn't functioned. It is need to repair the washer.



Hand pump is functioned. Water is yellow in color and has sand, clay and smell of mud. People are not using this well.

Water is milk in color and has no sand, no clay and no smell. People are using this well for washing.



Hand pump is functioned. Water is clean and has no sand, no clay and no smell. People are using this well for cooking and washing. Sometimes they are drinking.



- ✘ Closed Well
- ▲ New Well (Hand pump)
- Open Well
- Hand Pump
- ★ Private Well

Hand pump is functioned. But it is need to repair the handle. Water is clean and has no sand, no clay and no smell. People are using this well for cooking and washing. Sometimes they are drinking.

