


























Biweekly Field Report





Surveyor Zaw La
 Date visited 15 Jun 2018
 Time visited 16 : 15 am





Weather Condition Cloudy
 The last time of heavy raining Yesterday









| No | Item | Condition | Description and Photos |
|----|----------|---|---|
| 1 | (1) Well | Improved <input type="checkbox"/> Same <input checked="" type="checkbox"/> * Worse <input type="checkbox"/> <i>*as last week</i> | – Water from two open-wells is clean and can be used for drinking and living. There are eleven tube wells in the relocation site. People mainly use water from pipeline water distribution system so that no body use the tube wells and JET asked them to let know if the tube wells are needed to repair. |
| | | | <div style="display: flex; flex-wrap: wrap;"> <div style="width: 50%; text-align: center;">  <p>Open Well No. 1</p> </div> <div style="width: 50%; text-align: center;">  <p>Open Well No. 2</p> </div> <div style="width: 50%; text-align: center;">  <p>Tube Well No. 1</p> </div> <div style="width: 50%; text-align: center;">  <p>Tube Well No. 2</p> </div> <div style="width: 50%; text-align: center;">  <p>Tube Well No. 3</p> </div> <div style="width: 50%; text-align: center;">  <p>Tube Well No. 4</p> </div> <div style="width: 50%; text-align: center;">  <p>Tube Well No. 5</p> </div> <div style="width: 50%; text-align: center;">  <p>Tube Well No. 10</p> </div> </div> |

| | | | | |
|-----------------|---|--|---|--|
| | | |  <p>Tube Well No.7</p> |  <p>Tube Well No.6</p> |
| (2) Drainage | Improved <input type="checkbox"/> Same <input checked="" type="checkbox"/> * Worse <input type="checkbox"/> <i>*as last week</i> | | <p>– There is a little water in the drainage canals at the moment.</p> <p>Photos</p>  <p>Drain at the corner of Main Road A and B</p>  <p>Drain exit at the corner of Site village road and 2nd street</p>  <p>Drain exit at the corner of Site village road and 3rd</p>  <p>Drain exit at the corner of Site village road and Main Road C</p> | |
| (3) Road | Improved <input type="checkbox"/> Same <input checked="" type="checkbox"/> * Worse <input type="checkbox"/> <i>*as last week</i> | | <p>– All the roads are a bit wet, however no problem for walking.</p> <p>Photos</p>  <p>Main Road - B</p>  <p>1st Street</p> | |

| | | | | |
|--|--|--|---|---|
| | | |  <p>2nd Street Upper Block</p> |  <p>2nd Street Lower Block</p> |
| | | |  <p>3rd Street Upper Block</p> |  <p>3rd Street Lower Block</p> |
| | | |  <p>4th Street Upper Block</p> |  <p>4th Street Lower Block</p> |
| | | |  <p>5th Street</p> |  <p>6th Street</p> |
| | | |  <p>7th Street</p> |  <p>Site Village Road</p> |

| | | | | |
|-----------------------------|---|--|---|---|
| (4) Garbage Condition | Improved <input type="checkbox"/> Same <input checked="" type="checkbox"/> * Worse <input type="checkbox"/> <i>*as last week</i> | <ul style="list-style-type: none"> – People throw garbage beside the creek and even in front of their houses before they got enough garbage bins. – There are fourteen garbage bins are provided and they are kept at the corner of each road until the end of April and now all the garbage bins are kept in the communal compound near side road C by PAP community leader. During this raining season, people must keep garbage in its own house until the garbage collection car is coming. <p>Photos</p> | | |
| | | |  <p>Rubbish at the creek near 1st street</p> |  <p>Rubbish at the creek near 2nd street</p> |
| | | |  <p>Rubbish at the creek near Main Road C</p> |  <p>Rubbish at the creek near 6th Street</p> |

| <p>(5) Fly proof toilet</p> | <p>Improved <input type="checkbox"/> Same <input checked="" type="checkbox"/>* Worse <input type="checkbox"/> <i>*as last week</i></p> | <ul style="list-style-type: none"> - All of the fly proof toilets are used by people. - The four toilets had been repaired since April and the rest ones are repairing now by two local constructors from PAPs. <table border="1" data-bbox="552 241 1235 539"> <thead> <tr> <th rowspan="2">Condition</th> <th colspan="2">No. of HHs</th> </tr> <tr> <th>This week condition</th> <th>Previous week condition</th> </tr> </thead> <tbody> <tr> <td>Level 1</td> <td>59</td> <td>59</td> </tr> <tr> <td>Level 2</td> <td>32</td> <td>32</td> </tr> <tr> <td>Level 3</td> <td>0</td> <td>0</td> </tr> <tr> <td>Level 4</td> <td>0</td> <td>0</td> </tr> <tr> <td>No Toilet</td> <td>0</td> <td>0</td> </tr> </tbody> </table> <p><Evaluation Criteria> Level 1 - Fly proof toilet is not needed to be repaired. -No/rarely toilet unavailable Level 2 - Fly proof toilet is needed to be repaired. -Rarely toilet unavailable Level 3 -- Fly proof toilet is needed to be repaired. -Often toilet unavailable -As the result of filling the soil and also due to the heavy rain, some toilets are inconvenience to use. Level 4 - Fly proof toilet is urgently needed to be repaired. -Often toilet unavailable</p> <p>Photos</p> <div style="display: flex; flex-wrap: wrap;"> <div style="width: 50%; text-align: center;">  <p>House No. 81</p> </div> <div style="width: 50%; text-align: center;">  <p>House No. 37</p> </div> <div style="width: 50%; text-align: center;">  <p>House No. 31</p> </div> <div style="width: 50%; text-align: center;">  <p>House No. 21</p> </div> </div> | Condition | No. of HHs | | This week condition | Previous week condition | Level 1 | 59 | 59 | Level 2 | 32 | 32 | Level 3 | 0 | 0 | Level 4 | 0 | 0 | No Toilet | 0 | 0 |
|-----------------------------|---|---|-----------|------------|--|---------------------|-------------------------|---------|----|----|---------|----|----|---------|---|---|---------|---|---|-----------|---|---|
| Condition | No. of HHs | | | | | | | | | | | | | | | | | | | | | |
| | This week condition | Previous week condition | | | | | | | | | | | | | | | | | | | | |
| Level 1 | 59 | 59 | | | | | | | | | | | | | | | | | | | | |
| Level 2 | 32 | 32 | | | | | | | | | | | | | | | | | | | | |
| Level 3 | 0 | 0 | | | | | | | | | | | | | | | | | | | | |
| Level 4 | 0 | 0 | | | | | | | | | | | | | | | | | | | | |
| No Toilet | 0 | 0 | | | | | | | | | | | | | | | | | | | | |
| <p>(6) Electricity</p> | <p>Improved <input type="checkbox"/> Same <input checked="" type="checkbox"/>* Worse <input type="checkbox"/> <i>*as last week</i></p> | <ul style="list-style-type: none"> - Electricity comes regularly. - Electric poles and transformer are being supported with a good foundation. - There are some pieces of wood under an electric pole of main road B need to be cleaned. <p>Photos</p> | | | | | | | | | | | | | | | | | | | | |

| | | |  <p>Transformer No. 1</p> |  <p>Transformer No. 2</p> |
|----|-----------------------|---------------------------------|---|--|
| | | |  <p>Transformer No. 3</p> |  <p>Electricity poles of Main Road B and Road No. 3</p> |
| No | Item | Condition | Description and Photos | |
| 2 | (1)House Construction | No. of houses not completed (4) | <ul style="list-style-type: none"> – House No.9, there are three houses that planned to build in plot number 9 and 10 as the plots are owned by father and son. The two houses finished construction and left one. – House No.64, the house construction seems to be stopped. – House No. 78, the house need to be carried on construction, however PAPs are living now. – House No. 66, the house construction for first floor has been finished and the second floor is needed to be carried on. <p>Photos</p> | |
| | | |  <p>House No. 9</p> |  <p>House No. 64</p> |
| | | |  <p>House No. 78</p> |  <p>House No. 66</p> |
| 3 | Other Issues | | | |

(1). Drainage condition for rain water in their compounds

Description

| Condition | No. of HHs | |
|-----------|---------------------|-------------------------|
| | This week condition | Previous week condition |
| Level 1 | 87 | 87 |
| Level 2 | 3 | 4 |
| Level 3 | 0 | 0 |
| Level 4 | 1 | 0 |

<Evaluation Criteria>

Level 1

-No mud and no standing water with their own drainage system in their compound

Level 2

-No mud and no standing water in their compound

Level 3

- Some or little mud and standing water in their compound

Level 4

-A lot of mud and standing water in their compound

Photos



(2) Plantation

- In front of their compounds, the people planted shady trees, fruit trees, vegetables and floral plants.



Description

-In front of their compounds, the people planted shady trees, fruit trees, vegetables and floral plants.

| Type | No. of HHs | Remarks |
|--------------|------------|---|
| Shady tree | 15 | Albizzia, Indian almond, neem tree, etc. HH No. 20, 40, 43, 48, 51, 57, 59, 61, 62, 67, 69, 72, 73, 77, 85 |
| Fruit tree | 37 | Banana, Mango, sugarcane, coconut, citrus, jack fruit etc. HH No. 3, 15, 17, 20,21, 23, 28, 30, 31, 32, 34, 37, 40, 41, 48, 51, 52, 55, 57, 58, 59, 61, 62, 63, 67, 68, 70, 71, 72, 73, 77, 78, 82, 85, 86, 88 |
| Vegetable | 20 | Chili, tomato, bitter gourd, Roselle, gourd, basils, eggplant etc. HH No. 12, 17, 21, 41, 49, 58, 59, 61, 62, 63, 67, 68, 70, 71, 72, 73, 77, 82, 85, 86 |
| Floral plant | 31 | Jasmine, poinsettia, orchid, kiss me quick, etc. HH No. 3, 5, 6, 8, 10, 12, 13, 14, 17, 20, 21, 22, 23, 29, 30, 31, 32, 46, 48, 58, 59, 61, 62, 65, 67, 68, 69, 72, 77, 78, 86 |

Photos



| (3) Livestock | Description -The people are raising chicken, geese, ducks and pigs. | | | | | | | | | | | | | |
|---------------|--|---|------------|---------|---------|---|-------------------------------|-----|---|------------------|-------|---|---------------|--|
| | <table border="1"> <thead> <tr> <th>Type</th> <th>No. of HHs</th> <th>Remarks</th> </tr> </thead> <tbody> <tr> <td>Chicken</td> <td>6</td> <td>HH No. 13, 14, 21, 59, 67, 78</td> </tr> <tr> <td>Pig</td> <td>3</td> <td>HH No. 2, 21, 56</td> </tr> <tr> <td>Goose</td> <td>2</td> <td>HH No. 40, 67</td> </tr> </tbody> </table> | Type | No. of HHs | Remarks | Chicken | 6 | HH No. 13, 14, 21, 59, 67, 78 | Pig | 3 | HH No. 2, 21, 56 | Goose | 2 | HH No. 40, 67 | |
| Type | No. of HHs | Remarks | | | | | | | | | | | | |
| Chicken | 6 | HH No. 13, 14, 21, 59, 67, 78 | | | | | | | | | | | | |
| Pig | 3 | HH No. 2, 21, 56 | | | | | | | | | | | | |
| Goose | 2 | HH No. 40, 67 | | | | | | | | | | | | |
| | Photos | | | | | | | | | | | | | |
| |  <p>House No. 67</p> |  <p>House No. 12</p> | | | | | | | | | | | | |