

Weekly Field Report

No. 28


Surveyor: Zaw La

Date Visited: 11.5.2015






Time Visited: 9:30to 10:30


Weather Condition: Sunny


The last time of heavy raining: -





No	Item	Condition	Description and Photos
1	Condition of -		
	(1). Well	Improved <input checked="" type="checkbox"/> * Same <input type="checkbox"/> Worse <input type="checkbox"/> <i>*as last week</i>	Description & Photos: -See ANNEX.1 - Two wells and all hand pumps except near transformer are well functioned, clean water and enough water amount to use as the raining season is nearer and underground water level is raising up. Therefore no problem has heard so far.
	(2). Drainage	Improved <input type="checkbox"/> Same <input checked="" type="checkbox"/> * Worse <input type="checkbox"/> <i>*as last week</i>	<p><u>Description</u> -Water level in the drainage canal is near to the bottom.</p> <p><u>Photos</u></p>  <p>The above 4 pictures are shown before repairing situation. The rest of 2 pictures are shown current situation. The stream was repaired and it supposed to be smooth water flow and not be flooded in this year.</p>


	(3). Road	Improved <input type="checkbox"/> Same <input checked="" type="checkbox"/> * Worse <input type="checkbox"/> <i>*as last week</i>	<u>Description</u> -The roads are almost dry and no problem for traffic as a whole.
			<u>Photos</u> 
	(4). Garbage Condition	Improved <input type="checkbox"/> Same <input checked="" type="checkbox"/> * Worse <input type="checkbox"/>	<u>Description</u> -Garbage pit is used by people. -Garbage pit is over full. -There are some smells from garbage pit. -People throw garbage at the backside of Third Row. <div style="display: flex; flex-wrap: wrap;"> <div style="width: 50%; text-align: center;">  <p>Garbage Pit</p> </div> <div style="width: 50%; text-align: center;">  <p>Garbage Pit</p> </div> <div style="width: 50%; text-align: center;">  <p>Garbage Pit</p> </div> <div style="width: 50%; text-align: center;">  <p>Garbage at the backside of Third Row</p> </div> </div>

			 																				
No	Item	Condition	Description and Photos																				
1	(5). Fly proof toilet	Improved <input type="checkbox"/> Same <input checked="" type="checkbox"/> * Worse <input type="checkbox"/> <i>*as last week</i>	<p><u>Description</u> -All of fly proof toilets are used by people.</p> <table border="1"> <thead> <tr> <th rowspan="2">Condition</th> <th colspan="2">No. of HHs</th> </tr> <tr> <th>This week condition</th> <th>Previous week condition</th> </tr> </thead> <tbody> <tr> <td>Level 1</td> <td>42</td> <td>42</td> </tr> <tr> <td>Level 2</td> <td>21</td> <td>21</td> </tr> <tr> <td>Level 3</td> <td>0</td> <td>0</td> </tr> <tr> <td>Level 4</td> <td>0</td> <td>0</td> </tr> <tr> <td>No Toilet</td> <td>5</td> <td>5</td> </tr> </tbody> </table> <p><Evaluation Criteria> Level 1 -No need to repair fly proof toilet -No/rarely toilet unavailable Level 2 -Need to repair fly proof toilet -Rarely toilet unavailable Level 3 -Need to repair fly proof toilet -Often toilet unavailable Level 4 -Need to repair urgently fly proof toilet -Often toilet unavailable</p> <p><u>Photos</u></p>   	Condition	No. of HHs		This week condition	Previous week condition	Level 1	42	42	Level 2	21	21	Level 3	0	0	Level 4	0	0	No Toilet	5	5
Condition	No. of HHs																						
	This week condition	Previous week condition																					
Level 1	42	42																					
Level 2	21	21																					
Level 3	0	0																					
Level 4	0	0																					
No Toilet	5	5																					
	(6). Electricity	Improved <input type="checkbox"/> Same <input checked="" type="checkbox"/> * Worse <input type="checkbox"/>	<p><u>Description</u> -Electricity comes regularly. -Electric poles and transformer are supported in good foundation.</p>																				

		*as last week	<p><u>Photos</u></p> 
--	--	---------------	---

No	Item	Condition	Description and Photos
2	House Construction	No. of houses not completed (2)	<p><u>Description</u></p> <p>-HH No.1 is being repaired as a whole and it will suppose to be finished within next week.</p> <p>-In HH No.5, the construction for kitchen, toilet and water tank seems stopped.</p> <p><u>Photos</u></p> 
3	Living Status of PAPs (Sold house, renting, etc.)	<p><u>Description</u></p> <p>(1) House ownership</p> <p>(1)-1 No. of house that are owned by PAPs (48)</p> <p>(1)-2 No. of house that were sold (20)</p> <p>(2) Living condition</p> <p>(2)-1 No. of houses where PAPs live (38)</p> <p>(2)-2 No. of houses where not original PAPs lives (22)</p> <p>(2)-3 No. of houses where nobody lives (8)</p>	<p>Location Map: See ANNEX.2</p>

4	Other issues	<p>(1). Drainage condition for rain water in their compounds</p> <p><u>Description</u> -Rainy season is over. -Most of the compounds are almost dry.</p> <table border="1" data-bbox="451 317 998 541"> <thead> <tr> <th rowspan="2">Condition</th> <th colspan="2">No. of HHs</th> </tr> <tr> <th>This week condition</th> <th>Previous week condition</th> </tr> </thead> <tbody> <tr> <td>Level 1</td> <td>14</td> <td>14</td> </tr> <tr> <td>Level 2</td> <td>54</td> <td>54</td> </tr> <tr> <td>Level 3</td> <td>0</td> <td>0</td> </tr> <tr> <td>Level 4</td> <td>0</td> <td>0</td> </tr> </tbody> </table> <p><Evaluation Criteria> Level 1 -No mud and no standing water with their own drainage system in their compound Level 2 -No mud and no standing water in their compound Level 3 - Some or little mud and standing water in their compound Level 4 -A lot of mud and standing water in their compound</p> <div style="display: flex; flex-wrap: wrap;"> <div style="width: 50%; text-align: center;">  <p>HH No. 47</p> <p>Level 1</p> </div> <div style="width: 50%; text-align: center;">  <p>HH No. 14</p> <p>Level 2</p> </div> <div style="width: 50%; text-align: center;">  <p>HH No. 52</p> <p>Level 2</p> </div> <div style="width: 50%; text-align: center;">  <p>HH No. 11</p> <p>Level 2</p> </div> </div>	Condition	No. of HHs		This week condition	Previous week condition	Level 1	14	14	Level 2	54	54	Level 3	0	0	Level 4	0	0
Condition	No. of HHs																		
	This week condition	Previous week condition																	
Level 1	14	14																	
Level 2	54	54																	
Level 3	0	0																	
Level 4	0	0																	
4	(2) Plantation	<p><u>Description</u> -In front of their compounds, they planted shady trees, fruit trees, vegetables and floral plants.</p> <table border="1" data-bbox="451 1759 1365 1896"> <thead> <tr> <th>Type</th> <th>No. of HHs</th> <th>Remarks</th> </tr> </thead> <tbody> <tr> <td>Shady tree</td> <td>12</td> <td>Albizia, Indian almond, etc. HH No. 2, 3, 14, 19, 20, 21, 25, 27, 29, 32, 41 and 65</td> </tr> </tbody> </table>	Type	No. of HHs	Remarks	Shady tree	12	Albizia, Indian almond, etc. HH No. 2, 3, 14, 19, 20, 21, 25, 27, 29, 32, 41 and 65											
Type	No. of HHs	Remarks																	
Shady tree	12	Albizia, Indian almond, etc. HH No. 2, 3, 14, 19, 20, 21, 25, 27, 29, 32, 41 and 65																	

		<table border="1"> <tr> <td>Fruit tree</td> <td>24</td> <td>Banana, Mango, sugarcane, coconut, citrus, etc. HH No. 2, 3, 4, 7, 8, 9, 11, 17, 21,24, 25, 27, 33, 37, 38, 39, 41, 43, 45, 46, 47, 48, 54 and 65</td> </tr> <tr> <td>Vegetable</td> <td>10</td> <td>Spices, peas, roselle, etc. HH No. 22, 23, 25, 27, 38, 39, 40, 42,45 and 63</td> </tr> <tr> <td>Floral plant</td> <td>20</td> <td>Many species. HH No. 2, 9, 14, 15, 17,21, 23, 27, 32, 33, 38, 39, 40, 41, 42, 43, 47, 48, 58 and 65</td> </tr> </table>	Fruit tree	24	Banana, Mango, sugarcane, coconut, citrus, etc. HH No. 2, 3, 4, 7, 8, 9, 11, 17, 21,24, 25, 27, 33, 37, 38, 39, 41, 43, 45, 46, 47, 48, 54 and 65	Vegetable	10	Spices, peas, roselle, etc. HH No. 22, 23, 25, 27, 38, 39, 40, 42,45 and 63	Floral plant	20	Many species. HH No. 2, 9, 14, 15, 17,21, 23, 27, 32, 33, 38, 39, 40, 41, 42, 43, 47, 48, 58 and 65						
Fruit tree	24	Banana, Mango, sugarcane, coconut, citrus, etc. HH No. 2, 3, 4, 7, 8, 9, 11, 17, 21,24, 25, 27, 33, 37, 38, 39, 41, 43, 45, 46, 47, 48, 54 and 65															
Vegetable	10	Spices, peas, roselle, etc. HH No. 22, 23, 25, 27, 38, 39, 40, 42,45 and 63															
Floral plant	20	Many species. HH No. 2, 9, 14, 15, 17,21, 23, 27, 32, 33, 38, 39, 40, 41, 42, 43, 47, 48, 58 and 65															
		<p><u>Photos</u></p> 															
4	(3) Livestock	<p><u>Description</u></p> <p>-They are raising chicken, ducks, goats, pigs and cows. -Even though they have cows, they do not keep their cows in relocation site instead they keep in their farms or other places.</p> <table border="1"> <thead> <tr> <th>Type</th> <th>No. of HHs</th> <th>Remarks</th> </tr> </thead> <tbody> <tr> <td>Cow</td> <td>5</td> <td>HH No. 3, 18, 42, 47 and 54</td> </tr> <tr> <td>Pig</td> <td>-</td> <td>-</td> </tr> <tr> <td>Goat</td> <td>1</td> <td>HH.47</td> </tr> <tr> <td>Chicken and ducks</td> <td>15</td> <td>HH No. 4, 8, 12, 14, 28, 30, 32, 41, 47, 50, 51, 52, 55, 56 and 62</td> </tr> </tbody> </table>	Type	No. of HHs	Remarks	Cow	5	HH No. 3, 18, 42, 47 and 54	Pig	-	-	Goat	1	HH.47	Chicken and ducks	15	HH No. 4, 8, 12, 14, 28, 30, 32, 41, 47, 50, 51, 52, 55, 56 and 62
Type	No. of HHs	Remarks															
Cow	5	HH No. 3, 18, 42, 47 and 54															
Pig	-	-															
Goat	1	HH.47															
Chicken and ducks	15	HH No. 4, 8, 12, 14, 28, 30, 32, 41, 47, 50, 51, 52, 55, 56 and 62															

		<p><u>Photos</u></p>  <p>The first photograph shows a group of geese, including an adult and several young goslings, in an outdoor enclosure. The second photograph shows a person standing in a field with several black goats.</p>
5	Remarks	

ANNEX.1


As of 11.5.2015

Water is clean and has no sand, no clay and no smell. People use this well for cooking and washing. Sometimes they drink. But It need to be set up a set of a pulley wheel, bucket and a rope for convenience using the well.




Hand pump isn't functioned.

The well is in good situation. No smell. Water is clean and people living nearby are using this well. But It need to be set up a set of a pulley wheel, bucket and a rope for convenience using the well.



This hand pump is functioned very well. Water is clean and everyone nearby using this hand pump.

This hand pump is also functioned very well. Water is clean and everyone nearby using this hand pump.



This hand pump is also functioned very well. Water is clean and everyone living nearby using this hand pump. Now the raining season is going to be started and the underground water level is raising up and therefore the amount of having clean water is pretty enough to use.

This hand pump is also functioned very well. Water is clean and everyone living nearby using this hand pump. Now the raining season is going to be started and the underground water level is raising up and therefore the amount of having clean water is pretty enough to use.

- Closed Well
- New Well (Hand pump)
- Open Well
- Hand Pump
- Private Well

