

Weekly Field Report

No. 8


Surveyor: Sithu Nyein




Date Visited: 07.10.2014







Time Visited: 10:00 to 11:30


Weather Condition: Sunny


The last time of heavy raining: ___ -

No	Item	Condition	Description and Photos
1	Condition of -		
	(1). Well	Improved <input type="checkbox"/> Same <input checked="" type="checkbox"/> * Worse <input type="checkbox"/> <i>*as last week</i>	Description & Photos: -See ANNEX.1 -Hand Pumps of Well No.6 and 11 are needed to repair.
	(2). Drainage	Improved <input type="checkbox"/> Same <input checked="" type="checkbox"/> Worse <input type="checkbox"/> <i>*as last week</i>	<p><u>Description</u> -Water level in the drainage canal is near to the bottom.</p> <p><u>Photos</u></p> 
	(3). Road	Improved <input type="checkbox"/> Same <input checked="" type="checkbox"/> * Worse <input type="checkbox"/> <i>*as last week</i>	<p><u>Description</u> -The roads are almost dry and no problem for traffic as a whole.</p>

			<p><u>Photos</u></p> 
(4). Garbage Condition	<p>Improved <input type="checkbox"/></p> <p>Same <input checked="" type="checkbox"/></p> <p>Worse <input type="checkbox"/></p>	<p><u>Description</u></p> <ul style="list-style-type: none"> -Garbage pit is used by people. -Smells are emerging from garbage pit. -Garbage pit is full. -Small path between the garbage pit and road No.2 is renovated by putting soil on last Sunday 5th Oct, 2014 by village tract administrator. (see photo below) 	 

No	Item	Condition	Description and Photos																				
1	(5). Fly proof toilet	Improved <input type="checkbox"/> Same <input checked="" type="checkbox"/> Worse <input type="checkbox"/> <i>*as last week</i>	<p><u>Description</u> -All of fly proof toilets are being used by people.</p> <table border="1"> <thead> <tr> <th rowspan="2">Condition</th> <th colspan="2">No. of HHs</th> </tr> <tr> <th>This week condition</th> <th>Previous week condition</th> </tr> </thead> <tbody> <tr> <td>Level 1</td> <td>42</td> <td>42</td> </tr> <tr> <td>Level 2</td> <td>21</td> <td>21</td> </tr> <tr> <td>Level 3</td> <td>0</td> <td>0</td> </tr> <tr> <td>Level 4</td> <td>0</td> <td>0</td> </tr> <tr> <td>No Toilet</td> <td>5</td> <td>5</td> </tr> </tbody> </table> <p><Evaluation Criteria> Level 1 -No need to repair fly proof toilet -No/rarely toilet unavailable Level 2 -Need to repair fly proof toilet -Rarely toilet unavailable Level 3 -Need to repair fly proof toilet -Often toilet unavailable Level 4 -Need to repair urgently fly proof toilet -Often toilet unavailable</p> <p><u>Photos</u></p>   	Condition	No. of HHs		This week condition	Previous week condition	Level 1	42	42	Level 2	21	21	Level 3	0	0	Level 4	0	0	No Toilet	5	5
Condition	No. of HHs																						
	This week condition	Previous week condition																					
Level 1	42	42																					
Level 2	21	21																					
Level 3	0	0																					
Level 4	0	0																					
No Toilet	5	5																					
	(6). Electricity	Improved <input type="checkbox"/> Same <input checked="" type="checkbox"/> [*] Worse <input type="checkbox"/> <i>*as last week</i>	<p><u>Description</u> -Electricity is coming regularly -Electric poles and transformer are supported in good foundation.</p> <p><u>Photos</u></p>   																				

No	Item	Condition	Description and Photos																	
2	House Construction	No. of houses not completed (2)	<p><u>Description</u> -HH No.1 doesn't have ladder and nobody is living -In HH No.5, the construction for kitchen, toilet and water tank seems stopped. Nobody lives.</p> <p><u>Photos</u></p> 																	
3	Living Status of PAPs (Sold house, renting, etc.)	<p><u>Description</u> (1) House ownership (1)-1 No. of house that are owned by PAPs (49) (1)-2 No. of house that were sold (19) (2) Living condition (2)-1 No. of houses where PAPs live (37) (2)-2 No. of houses where not original PAPs lives (26) (2)-3 No. of houses where nobody lives (5)</p>	<p>Location Map: See ANNEX.2</p>																	
4	Other issues		<p>(1). Drainage condition for rain water in their compounds</p> <p><u>Description</u> -In most of the compounds, they become dry because of less rain.</p> <table border="1" data-bbox="400 1285 987 1525"> <thead> <tr> <th rowspan="2">Condition</th> <th colspan="2">No. of HHs</th> </tr> <tr> <th>This week condition</th> <th>Previous week condition</th> </tr> </thead> <tbody> <tr> <td>Level 1</td> <td>12</td> <td>12</td> </tr> <tr> <td>Level 2</td> <td>38</td> <td>32</td> </tr> <tr> <td>Level 3</td> <td>12</td> <td>16</td> </tr> <tr> <td>Level 4</td> <td>6</td> <td>8</td> </tr> </tbody> </table> <p><Evaluation Criteria> Level 1 -No mud and no standing water with their own drainage system in their compound Level 2 -No mud and no standing water in their compound Level 3 - Some or little mud and standing water in their compound Level 4 -A lot of mud and standing water in their compound</p>	Condition	No. of HHs		This week condition	Previous week condition	Level 1	12	12	Level 2	38	32	Level 3	12	16	Level 4	6	8
Condition	No. of HHs																			
	This week condition	Previous week condition																		
Level 1	12	12																		
Level 2	38	32																		
Level 3	12	16																		
Level 4	6	8																		



4 (2)
Plantation

Description

-In front of their compounds, they planted shady trees, fruit trees, vegetables and floral plants.

Type	No. of HHs	Remarks
Shady tree	12	Albizia, Indian almond, etc. HH No. 2, 3, 14, 19, 20, 21, 25, 27, 29, 32, 41 and 65
Fruit tree	24	Banana, Mango, sugarcane, coconut, citrus, etc. HH No. 2, 3, 4, 7, 8, 9, 11, 17, 21,24, 25, 27, 33, 37, 38, 39, 41, 43, 45, 46, 47, 48, 54 and 65
Vegetable	10	Spices, peas, roselle, etc. HH No. 22, 23, 25, 27, 38, 39, 40, 42,45 and 63
Floral plant	20	Many species. HH No. 2, 9, 14, 15, 17,21, 23, 27, 32, 33, 38, 39, 40, 41, 42, 43, 47, 48, 58 and 65

Photos





4 (3) Livestock

Description


-They are raising chicken, ducks, goats, pigs and cows.
 -Even though they have cows, they do not keep their cows in relocation site instead they keep in their farms or other places.

Type	No. of HHs	Remarks
Cow	5	HH No. 3, 18, 42, 47 and 54
Pig	1	HH No. 2
Goat	2	HH No. 50 and 51
Chicken and ducks	15	HH No. 4, 8, 12, 14, 28, 30, 32, 41, 47, 50, 51, 52, 55, 56 and 62

Photos



5 Remarks



Water is clean and has no sand, no clay and no smell. People are using this well for cooking and washing. Sometimes they are drinking



Hand pump is functioned. Water is clean and has no sand, no clay but it has smell of mud. People are using this well for washing.



Hand pump isn't functioned very well. The washer needs to be repaired. A lot of water needs to be poured every time before pumping. People are using this well for washing



Hand pump isn't functioned.

The color of water likes gray and has no sand, no clay and no smell. People are not using this well. Because nearby well No. 2 and 10 are used.



Hand pump is functioned. Water is clean, and has no sand, no clay but it has smell of mud. People are using this well for washing.



-  **Closed Well**
-  **New Well (Hand pump)**
-  **Open Well**
-  **Hand Pump**
-  **Private Well**

Hand pump is functioned. Water is clean and has no sand, no clay, and no smell. People are using this well for cooking and washing. Sometimes they are drinking.

